



## MAINTENANCE ALERT INDEX

The following is a numerical list of all active Maintenance Alerts. Check Effectivity column for Maintenance Alerts applicable to your Aircraft Model. Those not included are obsolete and will not be reissued.

MA NO.	C	C	C	C	C	SUBJECT	DATE	EFFECTIVITY
	P	P	P	P	P			
	1	2	3	4	5			
xxxx	X	X	X		X	PPG WINDSHIELD SEALANT	09-June-05	CUSTOM KIT 163
xxxx	X	X	X		X	TFLEX CABLE P/N 530585 – TRIM FLEX CABLE INSTALLATION	01-Mar-12	MODEL 500U SN 1531-1780, 500S SN 1755-3323 560F SN 893-1498, 680F SN 871-1447, 680FP SN 871-1447, 520 SN 17-150, 560A SN 231-330, 560E SN 331-892, 680 SN 500-730, 720 SN 501-892, 680E SN6 11-892, 680FL SN 1261-1853, 680FLP, SN 1048-1854, 680T SN 1473-1725, 680V SN 1519-1720, 680W SN 1720-1850 681 SN 6001-6072 685 SN 12000-12066 690 SN 11001-11099, 690A SN 11100-11344, 690B SN 11350-11566, 690C SN 111600-11735, 685A SN ALL, 685 SN 12061-12099, 690A SN 11282-11349, 690B 11350-11599, 690C 1160-11999, 690D SN 15000-15999 695 SN 95000-95999, 695A SN 96000-96200, 695B SN 96201-96999,
xxxx		X		X		CORROSION OF THE SKIN UNDER THE DORSAL FIN	02-Sept-11	MODEL 690A 410071-1 S/N 11100-11127 -501 S/N 11128-11193, 11195-11248, 11250-11268 690A 410073-1 & -501 S/N 11194, 11249, 11269-11349 690B 410073-503, -505, & -507 S/N 11350 & SUBS 690C 410080-1 S/N 11719 & SUBS 690D 410080-1 S/N 15001 & SUBS 695A 410080-1 S/N 96025 & SUBS
xxxx					X	CRACKS IN BOBWEIGHT SUPPORT ARMS	08-Mar-16	MODEL 690D, 695A, 695B
xxxx	X	X				CORROSION ON LOWER WING SKIN OUTSIDE OF SB208 INSPECTION AREA	19-Feb-21	MODEL 500U, 680FL, 680FLP, 680W S/N 1730 THRU 1854 500S S/N 1755 THRU 3323 681 S/N 6001 THRU 6072 685 S/N 12001 THRU 12066 690, 690A, 690B S/N 11001 THRU 11566

MA NO.	C C C C C P P P P P					SUBJECT	DATE	EFFECTIVITY
	1	2	3	4	5			
xxxx	X	X	X	X	X	TACHOMETER GENERATOR FLEX CABLE P/N 610217-501	17-May-22	MODEL ALL
xxxx					X	ALTERNATE TIRE ON MAIN LANDING GEAR	03-Aug-22  Cancelled 06-June-24	MODEL 690D S/N 15039-15042 695A S/N 96092-69100
xxxx		X			X	PART NUMBER 420077 RUDDER TORQUE HORN ASSEMBLY	03-Aug-22	MODEL 685/A, 690/A/B/C/D, 695/A/B
23001	X	X	X		X	INSPECTION FOR CRACKING IN LOWER WING SKINS AROUND MAIN LANDING GEAR (MLG) TRUSS CUTOUTS	24-July-23	MODEL 520, 560/A/E/F, 500/A/B/S/U, 680/E/F/FL/FLP/T/V/W ALL 681, 685, 690/A/B/C/D, 695/A/B ALL
23002		X	X		X	INSPECTION OF FLIGHT CONTROL AND TRIM CABLES	13-June-24	MODEL 680 FL/680 FL(P) ALL, 680T/V/W, 681, 685 ALL, 690/A/B/C/D ALL, 695/A/B ALL
24001	X	X				INSPECTION OF FLIGHT CONTROL AND TRIM CABLES	13-June-24	MODEL 500/A/B/U/S, 520, 560/A/E/F, 680/E/F/FP, 720, ALL
24002	X	X	X		X	HOW TO IDENTIFY "HEAVY" MAIN LANDING GEAR	15-Aug-24	MODEL 500/A/B/U/S, 560F, 680F/FP/FL/FL(P)/T/V/W, 681, 685, 690/A/B/C/D, 695/A/B, ALL
26001		X				PROPELLER INSTALLATION TORQUE VALUES	07-May-26	MODEL 500S S/N 3054 through 3323